



	Continued from previous page		Service No	13328
1 - MOTOR MIXING FLAP			318.23	20.00%
		Sub Total:	538.42	
Investigate Rattle between 2000-3000 rpm under lo	oad		120.00	20.00%
Replace Passenger side foot well air vent			60.00	20.00%
1 - FOOTWELL VENT R			52.01	20.00%
		Sub Total:	112.01	
Supply & Fit Number plates			30.00	20.00%
2 - NUMBER PLATE SINGLE			30.00	20.00%
		Sub Total:	60.00	
			Tota	1: 5,310.08

VAT Number: 940 9619 04 Data Protection (GDPR)

I agree and give my consent for JZM Porsche Ltd to have my contact details for Mot reminders and Marketing purposes, JZM will not pass this information on to any other 3rd Parties.

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights. All goods shall remain the property of the seller until paid for in full. Please note anything stored or parts removed for a vehicel without special arrangement will be disposed of after 1 month.

JZM Bank Details: Any payments made direct to our Bank account can you please quote your Surname & invoice number Barclays Bank A/c No : 83871754 Sort Code: 20-05-03 Swift Code for all accounts : BARCGB22 Iban Main Account: GB78 BARC 2005 0383 8717 54

Sub Total	£5,310.08
MOT: Standard	0.00
Retest	0.00
+ VAT Due	1,062.04
Invoice Total	£6,372.12
Total Deposits	0.00
Total Due	£6,372.12

			VAT Analysis
	С	ompany Reg. No. 06588591	VAT @ 20% on 5,310.08 = 1,062.02
Date	Signature	VAT No. 940 9619 04	