The Ferrari O mers' Club Concours Sports and by Lockton

21 July 2024

PLAIINUM

Certificate of Achievement

presented to

| Ferrari Tipo: | F40 | Registration: |
|---------------|-----|---------------|
| | | |

Chassis Number: 90353 Entrant:

The Ferrari here listed competed in the above event and when judged to the guidelines of the International Advisory Council for the Preservation of Ferrari Automobiles was awarded this standard.



Jonas

Set Bluenus




Club Secretary: Will Brown.

Chief Judge: Keith Bluemel



The Ferrari Owners Club Concours

sponsored by Lockton





EXTERIOR

CLASS 1: International

Judged by: Ian Barkaway & Iain Tyrell

1st Time Entrant:

| CLA | 55 1: International | | | 1st Time Entrant: | | |
|--------------------------|---------------------------|-------------|-----------------------------|-----------------------------|--|--|
| Reg | stration: | | | Tipo: F40 | | |
| CHAS | SIS: 90353 Colour: RED | | | Comments | | |
| Entrant Name: | | | | | | |
| | | MAX Begs | Actual Points senates | | | |
| A | COACHWORK Body & Wings | 5 | | | | |
| В | DOORS, BONNET, BOOT | 4 | 0.5 | Tarnished rear bumper stays | | |
| с тор | | 3 | | | | |
| D PAINT | | 5 | | | | |
| E PLATING Chrome | | 3 | | | | |
| F LIGHTS Condition | | 4 | 1 | Front lights misty | | |
| G | TRIM & EMBLEMS | 3 | | | | |
| Н | H GLASS, PLEXIGLASS | | | | | |
| i | RUBBER & WINDOW FELT | 3 | | | | |
| J Cleanliness | | | | | | |
| DED | UCTIONS: EXTERIOR - | 33 | 1.5 | | | |
| INTERIOR - 33 | | | 0 | | | |
| ENGINE/CHASSIS - 34 | | | 1 | | | |
| OVER RESTORATION PENALTY | | | | | | |
| TOTAL POINTS DEDUCTED | | | 2.5 | | | |
| | SCORE (100 LESS DEDUCTION | IS) | | 97.5 | | |



The Ferrari Owners Club Concours sponsored by Lockton

Goodwood Motor Circuit 21st July 2024



| VT | ERIOR | | | |
|----|---|---------------|------------------------------|---------------------|
| | | - | | |
| | | | | Comments |
| | | POINTS CFF | Actual Points deducted | |
| A | HEADLINER | 2 | | |
| В | UPHOLSTERY Seats, Console, Door & Shelf Panels | 4 | | |
| С | CARPET Pedals & Gear Lever | 2 | | |
| D | DASHBOARD Instruments & Components Condition | 3 | | |
| E | STEERING WHEEL Levers, Controls, Column | 2 | | |
| F | TRIM & EMBLEMS | 2 | | |
| G | WINDOWS Side, Vent, Rear Operation | 2 | | |
| н | BOOT Carpet, Paint, Decals, Hardware Originality | 2 | | |
| 1 | TOOLS Spare, Manual, Jack, Window Crank, Trouble Light | 4 | | |
| J | INSTRUMENTS clock, Radio, Lights: Dome, Door, Dash, Boot Operation | 5 | | |
| К | EXTERIOR LIGHTS Operation | 5 | | |
| L | Presentation & Cleanliness | | | Very well presented |
| | TOTAL DEDUCTIONS | 33 | 0 | |



The Ferrari Owners Club Concours sponsored by Lockton

Goodwood Motor Circuit 21st July 2024



| E | VGINE & CHASSIS | | | |
|---|---|----------------------|------------------------------|-------------------------|
| | | | | |
| | | - | | |
| | | | | |
| | | | | Comments |
| | | | | |
| | | MAX POINTS OFF | Actual Points deducted | |
| A | ENGINE Type | 5 | | |
| В | ENGINE Serial Number | 1 | | |
| С | ENGINE Transmission, Transaxle, Differential, Auxiliaries | 4 | | |
| D | FLUID LINES Oil, Fuel, Water | 3 | | |
| E | ELECTRICAL SYSTEM Components and Battery | 3 | | |
| F | FUEL SYSTEM Carburetors, Injection, Linkages | 2 | | |
| G | WHEELS & TYRES | 4 | | |
| Н | UNDERSIDE Wings and Frame | 2 | | |
| 1 | CHASSIS Brakes, Suspension Components | 3 | 1 | Chips on LH Front shock |
| J | EXHAUST Mufflers, Pipes, Cats, Hangers, Manifolds, Tailpipes | 2 | | |
| К | ENGINE OPERATION Smoothness & Leaks | 5 | | |
| L | Presentation & Cleanliness | | | |
| | TOTAL DEDUCTIONS | 34 | 1 | |



Suggested Maximum Deductions: EXTERIOR Abbreviations: Should be (SB), Not Original (NOR condition, design, craftsmanship), Inoperative (INOP)

| CATEGORY | Max | - 111111-011 | SIGNIFICANT | MAJOR | MAX DEDUCTION |
|--|-----|--|---|---|--|
| COACHWORK Body & Fenders | 5 | Small chips evidence of driving -0 Small metal finish flaws -1/2 Unobtrusive protective film -0 Period external mirrors -0 License plate frames -0 | Obtrusive chips -1 Significant dents -1 Each NOS bumper -1 Messy/discolored film -1 Obtrusive mirrors, frames, etc1 | Misshapen or modified body -3 Out of 10 year period rebody -3 Each missing bumper -2 Visible major rust -2 Some colored vinyl wrap -2 | Out of 10 year period rebody -5 (Pebble Beach) Major use of colored vinyl wrap -5 |
| DOORS, Bonnet Boot Fit & Operation | | Fit & finish not similar to original characteristics of the different coachwork houses -1/2 | Each door noticeably sagging -1 Each one NOR fit or operation -1 | X | All departing from the original fit and finish of the body maker -4 |
| ТОР | 3 | Stain or wear -1/2 | NOR style material -1 NOR shape, fit or frame -1 | NOR shape and fit -2 | NOR shape, fit & frame -3 Missing or INOP top -3 |
| PAINT | 5 | Minor scratches -1/2 Any period non-Ferrari color is acceptable -0 | Noticeable paint flaws -1 | Major paint flaws -3 | Serious deterioration -5 |
| PLATING Chrome | 3 | Scratches or blemishes -1/2 | Each one NOR quality -1 | X | Three NOR quality -3 |
| LIGHTS Condition | 4 | NOR style screws -1/2 Minor marker light NOR -1/2 Replacement bulbs -0 | Each NOR Lens or Housing -1 Each Light NOR fit or style -1 | Each NOR lens and housing -2 | All lights NOR -4 |
| TRIM Emblems | 3 | Scratches or blemishes -1/2 Slightly NOR appearance -1/2 | NOR Emblem -1 Missing Emblem -1 | X | All NOR or Missing -3 |
| GLASS PLEXIGLAS Condition | 3 | Small chips evidence of driving -0 Obtrusive chips or scratches -1/2 | Obtrusive breakage -1 Several obtrusive chips/scratches including convertible windows -1 | Replacement glass matching original characteristics -0 | No Glass or Plexiglas -3 NOR size -3 |
| UBBER Window Felt | | Tears or rips -1/2 Slightly NOR appearance -1/2 | Rubber or felt missing -1 Rubber or felt totally NOR type -1 | X | All missing -3 All totally NOR -3 |
| otal | 33 | | | | • |

X=Does Not Apply

International Advisory Council for Preservation of the Ferrari Automobile (IAC/PFA) \otimes 1994, 1999, 2015



Suggested Maximum Deductions: INTERIOR

Abbreviations: Should be (SB), Not Original (NOR condition, design, craftsmanship), Inoperative (INOP)

| CATEGORY | Max Ded | MINOR | SIGNIFICANT | MAJOR | MAX DEDUCTION |
|---|------------|---|---|---|---|
| HEADLINER | 2 | Stain or wear greater than patina 1/2 Small rips or tears -1/2 NOR Craftsmanship -1/2 | Not original design -1 Significant wear, rips or tears -1 | Reproduction materials NOR in appearance, design or workmanship -1 | No headliner -2 or NOR appearance, design |
| UPHOLSTERY Seats, Console, Door, Shelf, Panels | 4 | Stain or wear greater than patina -1/2 NOR craftsmanship -1/2 Small rips or tears -1/2 Period seatbelts, neat alarm, safety, communications equipment, -0 | Significant wear, rips or tears -1 Reproduction materials -1 NOR in appearance, design or workmanship -1 Obtrusive accessories -1 | Non-Ferrari seats -2 | & workmanship -2 No upholstery -2 or Most material, design & craftsmanship NOR on several components -4 |
| CARPET Pedal & Gear Lever | 2 | Stain or wear greater than patina -1/2 NOR style stitching/binding -1/2 NOR pattern/form pad or boot -1/2 NOR finishes or craftsmanship -1/2 | Missing heel pad or top boot -1 | Reproduction materials NOR in appearance, design or workmanship -1 | No carpet -2 or NOR appearance, design & workmanship -2 |
| DASHBOARD: All Instruments, Components | 3 | Small scratches/wear -1/2 Faded faces -1/2 NOR style paint or finish -1/2 | Significant scratches/wear -1 Holes or additional components -1 | Modified dashboard -2 | Dashboard & instruments totally modified , or deteriorated -3 |
| STEERING WHEEL | 2 | Small nicks or scratches -1/2 | Significant wear or scratches -1 Horn INOP -1 | Incorrect Ferrari wheel -1 | Incorrect wheel -2 (Non Ferrari/aftermarket) |
| TRIM & EMBLEMS | 2 | Poor plating or condition -1/2 Incorrect screws -1/2 | Each one NOR appearance or missing -1 | | Two missing or two NOR in appearance or design -2 |
| WINDOW Operation | 2 | Each sticky window -1/2 | Each window INOP -1 | Sunroof INOP -1 | Two INOP -2 |
| BOOT Carpet, Paint, Hardware, Decals | 2 | Stains or wear greater than patina -1/2 Small rips or tears -1/2 NOR style hardware or plating -1/2 | NOR style carpet or paint -1 Significant rips or tears -1 | | No carpet and/or paint -2 NOR materials, finish, style & craftsmanship -2 |
| TOOLS Spare, Manual, Crank, ack, Trouble Light | 4 | NOR wheel, tire, manual or pouch -1/2 NOR jack and tire tools for type -1/2 No window crank or trouble light -1/2 No warranty book, wipe rag -0 | Several missing tools or bag -1/2 No tools and bag -1 No manual and pouch -1 | No spare and wheel -1 No jack & changing tools -1 No puncture repair kit -1 | No tools, manuals, spare, jack and puncture repair -4 |
| NSTRUMENT Operation | 5 | Clock, radio, or dash light INOP -1/2 | Each instrument INOP -1 Heater Fan, air flow, AC INOP -1 | | Maximum -5 |
| XTERIOR LIGHTS Operation | 5 | Non-critical side marker INOP -1/2 License plate light INOP -1/2 | Each significant light INOP -1 | | Maximum -5 |
| otal | 33 | | | | |



Suggested Maximum Deductions: ENGINE & CHASSIS Abbreviations: Should be (SB), Not Original (NOR condition, type, finish), Inoperative (INOP)

| CATEGORY | Max Ded | MINOR | SIGNIFICANT | MAJOR | MAX DEDUCTION |
|---|------------|---|---|--|--|
| ENGINE Type | 5 | X | - | | |
| ENGINE Serial # | 1 | Unstamped blank serial # -0 | X | X | NOR engine for chassis -5 |
| | | onstaniped blank serial # -0 | Х | New Classiche engine -1 | NOR Serial # -1 |
| ENGINE Transmission, Transaxle, Differential, Auxiliaries | 4 | NOR finish/condition (minor) -1/2 Not neatly installed Auxiliary fan -1/2 | NOR auxiliaries -1 NOR finish/condition (major) -1 NOR transmission, transaxle, or differential -1 | Overall messy Engine & Auxiliaries -2 Several missing or NOR parts -2 | Multiple issues -4 |
| FLUID LINES Oil, Fuel, Water | 3. | NOR finish -1/2 | NOR lines -1 NOR finishes -1 | Several NOR lines -2 Several NOR finishes -2 Several missing/broken lines -3 | Multiple issues -3 |
| ELECTRICAL SYSTEM Components & Battery | 3 | NOR wire or finish -1/2 Corrosion -1/2 Replacement battery -0 Concealed battery charger -0 | NOR pieces -1 NOR finishes -1 | Overall messy, parts missing and/or NOR style -2 | Multiple issues -3 |
| FUEL SYSTEM Carburetors, Injection, Linkages | 2 | NOR finish -1/2 | Several NOR pieces -1 | × | Missing pieces -2 NOR carburetors or fuel injection- 2 |
| WHEELS & TIRES | 4 | NOR decal -1/2 NOR valve stem -1/2 Original spare -0 | NOR paint or plating -1 Damaged spoke -1 NOR tire profile -1 | Four NOR knock-offs -2 Four NOR wheels -2 Four NOR tire profiles -2 | Multiple issues -4 |
| JNDERSIDE Vings & Frame | 2 | NOR fender hardware -1/2 NOR frame hardware -1/2 Partial NOR finish -1/2 | NOR fender finish -1 NOR frame finish -1 | X | Multiple issues -2 |
| CHASSIS Brakes & Suspension | 3 | NOR finish -1/2 NOR plating -1/2 | Major NOR finish -1 Major NOR plating -1 | NOR hardware -2 | NOR components -3 |
| XHAUST Nufflers, Pipes, Cats, langers, Manifold | 2 | NOR hardware -1/2 NOR finish -1/2 NOR manifold -1/2 NOR resonator -1/2 | NOR muffler -1 NOR cat -1 | Two NOR mufflers -1 ½ Two NOR cats - 1 ½ Two NOR resonators - 1 | Total system NOR -2 |
| NGINE OPERATION moothness & Leaks | 5 | x | Running roughness -1 Oil, water, fuel seepage -1 | Misfiring -3 Visible, oil, fuel, water leak -3 | Won't run -5 |
| otal | 34 | | | | |

Not Apply

International Advisory Council for Preservation of the Ferrari Automobile (IAC/PFA) © 1994, 1999, 2015