



Rushton Hall, Northants 6th - 7th August 2022

EXTERIOR				JUDGED by:			
CLA	SS: MASTERS			1st Time Entrant:			
Reg	istration:			Tipo: F40			
CHAS	SSIS: 90353 Colour: Red			Comments			
Entra	int Name:						
		MAX POINTS OFF	Actual Points decision				
A	COACHWORK Body & Wings	5	0				
В	DOORS, BONNET, BOOT	4	0	N.S Headlight, water stains in bezel			
С	ТОР	3	0				
D	PAINT	5	0				
E	PLATING Chrome	3	0				
F	LIGHTS Condition	4	0				
G	TRIM & EMBLEMS	3	0				
Н	GLASS, PLEXIGLASS	3	0	Fingerprints above steering wheel on glass			
1	RUBBER & WINDOW FELT	3	0				
J	Cleanliness						
DED	UCTIONS: EXTERIOR -	33	0				
	INTERIOR -	33	0				
	ENGINE/CHASSIS -	34	0				
	OVER RESTORATION PENALTY		0				
	TOTAL POINTS DEDUCTED		0				
	SCORE (100 LESS DEDUCTIONS)			100			



Suggested Maximum Deductions: EXTERIOR Abbreviations: Should be (SB), Not Original (NOR condition, design, craftsmanship), Inoperative (INOP)

CATEGORY	Max MINOR Ded		SIGNIFICANT	MAJOR	MAX DEDUCTION
COACHWORK Body & Fenders	5	Small chips evidence of driving -0 Small metal finish flaws -1/2 Unobtrusive protective film -0 Period external mirrors -0 License plate frames -0	Obtrusive chips -1 Significant dents -1 Each NOS bumper -1 Messy/discolored film -1 Obtrusive mirrors, frames, etc1	Misshapen or modified body -3 Out of 10 year period rebody -3 Each missing bumper -2 Visible major rust -2 Some colored vinyl wrap -2	Out of 10 year period rebody -5 (Pebble Beach) Major use of colored vinyl wrap -5
DOORS, Bonnet Boot Fit & Operation	characteristics of the different Each one NOR fit or operation -1			X	All departing from the original fit and finish of the body maker -4
ТОР	3	Stain or wear -1/2	NOR style material -1 NOR shape, fit or frame -1	NOR shape and fit -2	NOR shape, fit & frame -3 Missing or INOP top -3
PAINT	Minor scratches -1/2 Any period non-Ferrari color is acceptable -0 Noticeable paint flaws -1		Major paint flaws -3	Serious deterioration -5	
PLATING Chrome	3	Scratches or blemishes -1/2	Each one NOR quality -1	X	Three NOR quality -3
LIGHTS Condition	4 NOR style screws -1/2 Each NOR Lens or Housing -1 Minor marker light NOR -1/2 Each Light NOR fit or style -1 Replacement bulbs -0			Each NOR lens and housing -2	All lights NOR -4
TRIM Emblems	3	Scratches or blemishes -1/2 Slightly NOR appearance -1/2	NOR Emblem -1 Missing Emblem -1	X	All NOR or Missing -3
GLASS PLEXIGLAS Condition	3	Small chips evidence of driving -0 Obtrusive chips or scratches -1/2	Obtrusive breakage -1 Several obtrusive chips/scratches including convertible windows -1	Replacement glass matching original characteristics -0	No Glass or Plexiglas -3 NOR size -3
RUBBER Window Felt	3	Tears or rips -1/2 Slightly NOR appearance -1/2	Rubber or felt missing -1 Rubber or felt totally NOR type -1	X	All missing -3 All totally NOR -3
Total	33				



CHARLES STANLEY Wealth Managers

Rushton Hall, Northants 6th - 7th August 2022

INT	ERIOR			
				Comments
		MAX POINTS OFF	Actual Points deducted	
A	HEADLINER	2	0	
В	UPHOLSTERY Seats, Console, Door & Shelf Panels	4	0	
С	CARPET Pedals & Gear Lever	2	0	
D	DASHBOARD Instruments & Components Condition	3	0	
E	STEERING WHEEL Levers, Controls, Column	2	0	
F	TRIM & EMBLEMS	2	0	
G	WINDOWS Side, Vent, Rear Operation	2	0	
Н	BOOT Carpet, Paint, Decals, Hardware Originality	2	0	
1	TOOLS Spare, Manual, Jack, Window Crank, Trouble Light	4	0	
J	INSTRUMENTS Clock, Radio, Lights: Dome, Door, Dash, Boot Operation	5	0	
K	EXTERIOR LIGHTS Operation	5	0	
L	Presentation & Cleanliness			
	TOTAL DEDUCTIONS	33	0	



Suggested Maximum Deductions: INTERIOR

Abbreviations: Should be (SB), Not Original (NOR condition, design, craftsmanship), Inoperative (INOP)

CATEGORY	Max Ded	MINOR	SIGNIFICANT	MAJOR	MAX DEDUCTION
			Not original design -1 Significant wear, rips or tears -1	Reproduction materials NOR in appearance, design or workmanship -1	No headliner -2 or NOR appearance, design & workmanship -2
UPHOLSTERY Seats, Console, Door, Shelf, Panels	4	Stain or wear greater than patina -1/2 NOR craftsmanship -1/2 Small rips or tears -1/2 Period seatbelts, neat alarm, safety, communications equipment, -0	Significant wear, rips or tears -1 Reproduction materials -1 NOR in appearance, design or workmanship -1 Obtrusive accessories -1	Non-Ferrari seats -2	No upholstery -2 or Most material, design & craftsmanship NOR on several components -4
CARPET Pedal & Gear Lever	CARPET 2 Stain or wear greater than patina -1/2 Missing heel pad or top boot -1 R NOR style stitching/binding -1/2 NOR patters/form pad or boot 1/2			Reproduction materials NOR in appearance, design or workmanship -1	No carpet -2 or NOR appearance, design & workmanship -2
DASHBOARD: All Instruments, Components Small scratches/wear -1/2 Faded faces -1/2 NOR style paint or finish -1/2 Significant scratches/wear -1 Holes or additional components -1		Modified dashboard -2	Dashboard & instruments totally modified , or deteriorated -3		
STEERING 2 Small nicks or scratches -1/2 WHEEL		Significant wear or scratches -1 Horn INOP -1	Incorrect Ferrari wheel -1	Incorrect wheel -2 (Non Ferrari/aftermarket)	
TRIM & EMBLEMS				Two missing or two NOR in appearance or design -2	
WINDOW Operation	2 Each sticky window -1/2 Each window INOP -1 Sunroof INOP -1		Sunroof INOP -1	Two INOP -2	
BOOT Carpet, Paint, Hardware, Decals	2	Stains or wear greater than patina -1/2 Small rips or tears -1/2 NOR style hardware or plating -1/2	NOR style carpet or paint -1 Significant rips or tears -1		No carpet and/or paint -2 NOR materials, finish, style & craftsmanship -2
TOOLS Spare, Manual, Crank, Jack, Trouble Light	NOR jack and tire tools for type -1/2 No tools and bag -		Several missing tools or bag -1/2 No tools and bag -1 No manual and pouch -1	No spare and wheel -1 No jack & changing tools -1 No puncture repair kit -1	No tools, manuals, spare, jack and puncture repair -4
INSTRUMENT Operation	5	Clock, radio, or dash light INOP -1/2	Each instrument INOP -1 Heater Fan, air flow, AC INOP -1		Maximum -5
EXTERIOR LIGHTS Operation	5	Non-critical side marker INOP -1/2 License plate light INOP -1/2	Each significant light INOP -1		Maximum -5
Total	33				





Rushton Hall, Northants 6th - 7th August 2022

EN	IGINE & CHASSIS			
				Comments
		MAX POINTS OFF	Actual Points desturied	
A	ENGINE Type	5	0	
В	ENGINE Serial Number	1	0	
С	ENGINE Transmission, Transaxle, Differential, Auxiliaries	4	0	
D	FLUID LINES Oil, Fuel, Water	3	0	
E	ELECTRICAL SYSTEM Components and Battery	3	0	
F	FUEL SYSTEM Carburetors, Injection, Linkages	2	0	
G	WHEELS & TYRES	4	0	
Н	UNDERSIDE Wings and Frame	2	0	
I	CHASSIS Brakes, Suspension Components	3	0	
J	EXHAUST Mufflers, Pipes, Cats, Hangers, Manifolds, Tailpipes	2	0	
К	ENGINE OPERATION Smoothness & Leaks	5	0	
L	Presentation & Cleanliness			
	TOTAL DEDUCTIONS	34	0	



Suggested Maximum Deductions: ENGINE & CHASSIS Abbreviations: Should be (SB), Not Original (NOR condition, type, finish), Inoperative (INOP)

CATEGORY	Max MINOR Ded		SIGNIFICANT	MAJOR	MAX DEDUCTION
ENGINE Type	5	X	X	X	NOR engine for chassis -5
ENGINE Serial #	1	Unstamped blank serial # -0	X	New Classiche engine -1	NOR Serial # -1
ENGINE Transmission, Transaxle, Differential, Auxiliaries	xle, Differential, ries Not neatly installed NOR finish, NOR transior differential NOR finish NOR transior differential NOR lines NOR lines		NOR auxiliaries -1 NOR finish/condition (major) -1 NOR transmission, transaxle, or differential -1	finish/condition (major) -1 Auxiliaries -2 Several missing or NOR parts -2	
FLUID LINES Oil, Fuel, Water			NOR lines -1 NOR finishes -1	Several NOR lines -2 Several NOR finishes -2 Several missing/broken lines -3	Multiple issues -3 Multiple issues -3
Components & Corrosion -1/2 Battery Replacement battery		NOR wire or finish -1/2 Corrosion -1/2 Replacement battery -0 Concealed battery charger -0	NOR pieces -1 NOR finishes -1	Overall messy, parts missing and/or NOR style -2	
FUEL SYSTEM Carburetors, Injection, Linkages	2	NOR finish -1/2	Several NOR pieces -1	X	Missing pieces -2 NOR carburetors or fuel injection- 2
NOR valve ster Original spare JNDERSIDE 2 NOR fender ha NOR frame ha		NOR decal -1/2 NOR valve stem -1/2 Original spare -0	NOR paint or plating -1 Damaged spoke -1 NOR tire profile -1	Four NOR knock-offs -2 Four NOR wheels -2 Four NOR tire profiles -2	Multiple issues -4
		NOR fender hardware -1/2 NOR frame hardware -1/2 Partial NOR finish -1/2	NOR fender finish -1 NOR frame finish -1	X	Multiple issues -2
CHASSIS Brakes & Suspension	Web 1 / 1/a		Major NOR finish -1 Major NOR plating -1	NOR hardware -2	NOR components -3
EXHAUST Mufflers, Pipes, Cats, Hangers, Manifold	2	NOR hardware -1/2 NOR finish -1/2 NOR manifold -1/2 NOR resonator -1/2	NOR muffler -1 NOR cat -1	Two NOR mufflers -1 ½ Two NOR cats - 1 ½ Two NOR resonators - 1	Total system NOR -2
ENGINE OPERATION Smoothness & Leaks	5	×	Running roughness -1 Oil, water, fuel seepage -1	Misfiring -3 Visible, oil, fuel, water leak -3	Won't run -5
Total	34				

X=Does Not Apply

International Advisory Council for Preservation of the Ferrari Automobile (IAC/PFA) © 1994, 1999, 2015

6th - 7th August 2022

PLATINUM

Certificate of Achievement

presented to

Ferrari Tipo: F40

Registration:

Chassis Number: 90353

Entrant:

The Ferrari here listed competed in the above event and when judged to the guidelines of the International Advisory Council for the Preservation of Ferrari Automobiles was awarded this standard.

CHARLES

Wealth Managers

What

Club Secretary: Will Brown.

Mul

Chief Judge: Andrew Seward

